



Charge Calculator Features



Features:

- ✚ Two Different Displays For spectraview and Charge calculator
- ✚ One display will show Spectrometer readings and other display will show the addition of Charge required
- ✚ Displays are interconnected with each other.
- ✚ Flexibility in choosing the number of Elements in display
- ✚ Flexibility in choosing display sizes 1", 2.3" or 4"

-
- + User interface to add recovery, Element for Addition, Furnace capacity**
 - + Logging of addition details and calculations**
 - + Password protection for addition or deletion for recovery elements.**
 - + Printing of Addition report using local printer attached to the Computer**
 - + Acknowledgment on Successful data transmission**
 - + Display of Company name in rolling Manner**